

2020

February

| MONDAY | TUESDAY | WEDNESDAY | THURSDAY | FRIDAY | SATURDAY | SUNDAY |
|--------|-----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|
| 27 | 28 | 29 | 30 | 31 | 01 | 02 Super Bowl Party 5:30pm |
| 03 | 04 | 05 | 06 | 07 | 08 | 09 |
| 10 | 11 Annual Meeting 2:00pm Cocktails at Pool 4:30pm Pizza and Salad 6:00pm | 12 | 13 Leak reported on the south driveway side at the garage entry | 14 Leak checked by Terrano Plumbing. Sewer pipe was clogged with paper towels and wipes. Posted issue to owners. | 15 | 16 |
| 17 | 18 | 19 | 20 | 21 | 22 | 23 Elevator went out of service around 4:30pm. Thyssenkrupp was contacted for emergency service. |
| 24 | 25 | 26 | 27 | 28 | 29 Sharon Dowling found the social room sink full of paper towel shreds and discovered the sink was clogged with paper towels! Terrano Plumbing was contacted. | 01 |
| 02 | 03 | Notes: The same board of directors will serve 2020. A sewer line back up occurred on the south side driveway by the garage entrance. No paper towels or wipes are to be flushed down the toilets. Posted information for owners. Someone clogged the social room kitchen sink and didn't report it. The sink was also leaking underneath. The grill needs some replacement parts. | | | | |