

# 2023

# June

MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY	SUNDAY
29	30	31	01	02	03	04
05 Pipe Lining Technologies onsite for preliminary work	06 Pipe Lining Technologies onsite for preliminary work	07 Pipe Lining Technologies onsite for preliminary work	08 Pipe Lining Technologies onsite for preliminary work	09	10	11
12 Pipe Lining Technologies onsite for pipe lining - water off Electric company onsite for switch change out on poles in front	13 Pipe Lining Technologies onsite for pipe lining- water off	14 Pipe Lining Technologies onsite for pipe lining- water off	15 Pipe Lining Technologies onsite for pipe lining- water off	16	17	18
19 Pipe Lining Technologies onsite for pipe lining - water off Electric company onsite for switch change out on poles in front	20 Pipe Lining Technologies onsite for pipe lining- water off	21 Pipe Lining Technologies onsite for pipe lining- water off	22 Pipe Lining Technologies onsite for pipe lining- water back on late afternoon. Elevator PH button not working and elevator went out of service.	23 Elevator PH button not working	24 Elevator PH button not working	25 Elevator PH button not working
26 Pipe Lining Technologies onsite for pipe lining- Unit 203 & Pool Bathroom. TK Elevator onsite to fix PH button. Pest Relief onsite for bi-monthly treatment.	27 Pipe Lining Technologies onsite for pipe lining- Unit 203 & Final Camera Run	28	29	30	01	02
03	04	<b>Notes:</b> The pipe lining project was a success. The main work was completed in 14 work days. Once we pass inspections, the openings in the garage floor will be filled. TK Elevator did not put the elevator back in service until around 9:30pm on the 22nd. The reported repair request for the PH button was not fixed. Another ticket was opened on the 23rd and TK Elevator did not show for the PH button repair until Monday, the 26th. Button 5 was sticking so both the PH and he 5 button were replaced. The display on 7 is not working properly and the part has been ordered. Owners had to get off on floor 7 and walk up the stairs to the top floor when the PH button was not functioning.				