

2021

August

MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY	SUNDAY
26	27	28	29	30	31	01
02 M.A. Construction onsite to put a cement slurry into the pool area void. The product still came out of the Aloha seawall so the job was immediately aborted.	03	04	05	06	07	08
09	10	11	12	13 FOB System not working. Worthington Security onsite to investigate and a motherboard needs replaced. Part ordered.	14	15
16 Board Meeting 5:00pm using Zoom Rapid Response onsite for Ficus white fly treatment	17	18	19	20 Worthington Security onsite to replace FOB System motherboard.	21	22
23	24	25	26 Pest Relief onsite for bi-monthly pest control treatment.	27 Garage Fob System relay stopped working. The elevator is not secure. Worthington Security onsite to investigate but could not determine issue.	28	29
30 Worthington Security onsite to continue garage Fob System troubleshooting with the manufacturer. The relay motherboard needs replaced. Part ordered.	31 Gentec onsite for annual fire alarm inspection.	Notes: Both motherboards in the FOB System went down this month. The main board replacement is around \$1700 and the relay motherboard is \$2700. Worthington Security suspects we had a lighting strike. The attempt to fill the pool area void with cement slurry did not work. The engineer and M.A. Construction will work on another solution.				