

# 2020

# June

MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY	SUNDAY
01	02	03	04	05	06	07
08	09	10	11	12	13	14
15 Board Meeting 5pm using Zoom Amazon Pest treated outdoor area for mosquitoes using a new granular product. Sewer pipe jetted with 4400 psi by Mark of JK Property.	16	17	18 Comcast Business upgraded social room box to HD	19	20	21
22 Fish Window Cleaning cleaned the catwalk railing glass and the lobby windows.	23 Andy's Awning Cleaning & Repair cleaned and sealed the pool canopy and the garage canopy. Amazon Termite & Pest did the annual termite inspection.	24	25	26 New social room bookcases built and old bookcases removed. New social room door purchased, told Mark of JK to get a permit and install.	27 Mark of JK ran another camera through the sewer pipe. He has found a problem for about a car length at the main cleanout area.	28
29	30	01	02	03	04	05
06	07	<b>Notes:</b> Comcast found that our social room hd box was never activated and that has been corrected. Five doors were treated for termites during the annual termite inspection. If anyone notices issues with their doors at any time, please contact Sharon Dowling for a treatment. The awnings were cleaned and sealed. New bookcases were purchased and built for the social room. A new door was purchased for the social room and Mark of JK has been instructed to get a permit and install the door. Amazon Pest used a new granular product to treat for mosquitoes at no charge. If it works well, we will add this to our annual pest control budget in the future. The sewer pipe was jetted a final time at 4400 psi and the camera was run through again. This time it shows a problem at the main clean out area for about a car length. Mark stated this is not an emergency situation so we will address this at the next board meeting.				