

2021

June

MONDAY	TUESDAY	WEDNESDAY	THURSDAY	FRIDAY	SATURDAY	SUNDAY
31	01	02	03	04	05	06
07	08	09 Bluewater Electric onsite to put the electrical outlet required in the meter room for the camera system.	10	11	12	13
14	15	16	17	18 Raj The Iquana Guy was onsite and caught 4 iquanas	19	20
21 Board Meeting 5:00pm using Zoom Bluewater Electric onsite to run the internet connection to the camera system.	22 Raj The Iquana Guy was onsite and set up traps. RWK Pump & Motor Repair onsite to check water pump room equipment. Pest Relief onsite for bi-monthly treatment.	23 Worthington onsite to complete the camera setup.	24	25 Sharon Dowling met with Southern Chute to get a quote for trash chute cleaning.	26 Sharon Dowling met with Sunshine Sprinkler about the front parking lot irrigation needs for the paving project. Met with a company NextGen sent to quote replacing the fire hose door levers.	27
28	29 Window Leaders onsite to clean building side windows.	30 Cleaner - Victor last day	01	02	03	04
05	06	Notes: Bluewater Electric finished the electrical and internet connection run required for the camera system. Worthington was contacted to return and finish the installation and provide instructions for viewing the camera images when needed. The irrigation company expected to do the parking lot improvements backed out due to lack of labor. The process has begun to call and set up appointments with other irrigation companies to select another provider to fix and enhance the parking lot irrigation. The pump room equipment needed an exhaust fine replaced. The camera installation is completed and we now have access to review images when necessary.				